



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT
Road History Data Sheet

General

Zone
DASARAHALLI

Street ID
W0464, W0601, W0476,
W0470, W0472, W0605

Segment No.
14/C-W0464/S062318

Ward No.

14

Street Name

NA, 2nd Crs, 3rd Crs

Total Length (m)

256.16

Ward Name

Bagalakunte

Significant Landmark

Mahalakshmi Nagara

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	117.68	77.493792	13.054705	77.494104	13.055724	10th cross	1st Cross
2	24.98	77.493755	13.055462	77.493980	13.055415	1st Cross	2nd Cross
3	113.50	77.493449	13.054498	77.493741	13.055483	1st Main	Dead end

Work Details

History of Road / Lane / Circles

Name of the Work

Improvements to roads and
drains at 10th cross
Mahalakshmi Nagara in
Bagalagunte Ward No 14

Sanctioned Estimated Amount (Rs.)

5000000

Sanctioned Year

2017-18

Year

2017 - 2018

Type of Work

Others

Other Work Type

CC Road

Tender

Not a Tender

Work Details

Job No. / Work Code

014-18-000043

Work Order No.

BBMP/EE/DD/WO/80/17-18

Work Order Date

20/11/2017

Defect Liability Period From

20/11/2017

Defect Liability
Period To

19/11/2018

Period of Extension

Multiple road involved with the
same Job No/ Work Code #

No

Contractor Details

Name of Contractor

KRIDL

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)

4992551.00

Phone No.

9449863064

E-Mail ID

Zone: DASARAHALLI

Ward No: 14

Ward Name: Bagalakunte

Street ID: W0464,

W0601,

W0476,

W0470,

W0472

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರ
ಇ.ದಾಸರಾಜ್ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಜಿಎಂಸಿ